

	Type Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
51	BRS 0	(Chhor-Khushraw-S.in. Moresco-Larry-L.in.) and @pd>20040309	USPAT; US-PGPUB; EPO; JPO	2004/07/13 09:04			0
52	BRS 185	(257/433.ccls. 257/679.ccls. 361/737.ccls. 902/25.ccls. 902/26.ccls. 902/29.ccls. 235/492.ccls. 235/441.ccls.) and @pd>20040309	USPAT; US-PGPUB	2004/07/13 13:14			0
53	BRS 11	((smart ic chip memory) near3 (card module) same (resin near5 mold\$3)) same (conduct\$3 connect\$3 terminal\$1 pad\$1 contact\$3) and @pd>20040309	USPAT; US-PGPUB	2004/07/13 10:34			0

	Type Hits	Search Text			DBs	Time Stamp	Comments	Error Definition	Errors
54	BRS 130	("3414892" "4500905" "4672577" "5001539" "5191405" "5227338" "5279029" "5369056" "5377077" "5422435" "5446620" "5455445" "5479318" "5484959" "5498906" "5523622" "5543664" "5561591" "5572065" "5585668" "5588205" "5612570" "5644161" "5693552" "5703747" "5780925" "5796164" "5828125" "5895232" "5945732" "5973951" "5985693"	"3432827" "4535424" "4710798" "5089862" "5202754" "5236117" "5283468" "5369058" "5398200" "5426566" "5448450" "5455740" "5481090" "5493476" "5499160" "5523628" "5550711" "5561622" "5581121" "5585675" "5592364" "5615475" "5654220" "5696031" "5745407" "5781031" "5801437" "5843807" "RE36229" "5960539" "5976953" "6025642"	"4489478" "4630096" "4811082" "5160987" "5221642" "5266912" "5367766" "5371866" "5420751" "5434745" "5453952" "5468997" "5481133" "5495398" "5502289" "5528075" "5552963" "5566051" "5581498" "5586009" "5605592" "5631193" "5654877" "5702985" "5778522" "5783464" "5804870" "5864175" "5915167" "5969380" "5978227" "6034882"	USPAT	2004/07/13 10:51			0
55	BRS 0	6731011.URPN.			USPAT	2004/07/13 11:26			0

	Type Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
56	BRS 2	(smart ic chip memory) near3 (card module) same (resin near5 mold\$3) same (conduct\$3 connect\$3 terminal\$1 pad\$1 contact\$3) and @pd>20040309	EPO; JPO; DERWENT; IBM_TDB	2004/07/13 12:43			0
57	BRS 5	((smart ic chip memory) near3 (card module) same (resin epoxy)) same (lead adj frame) and @pd>20040309	USPAT; US-PGPUB	2004/07/13 12:45			0
58	BRS 1	((smart ic chip memory) near3 (card module) same (resin epoxy)) same (lead adj frame) and @pd>20040309	EPO; JPO; DERWENT; IBM_TDB	2004/07/13 12:52			0
59	BRS 3	(smart ic chip memory) near3 (card module) same (plate near5 (thermal\$2 heat) near5 conductive) and @pd>20040309	USPAT; US-PGPUB	2004/07/13 12:53			0
60	BRS 2	(smart ic chip memory) near3 (card module) same (plate near5 (thermal\$2 heat conductive) near5 (packag\$3 resin cas\$3)) and @pd>20040309	USPAT; US-PGPUB	2004/07/13 12:56			0
61	BRS 5	(smart ic chip memory) near3 (card module) same (memory near5 controller near5 (single same one)) and @pd>20040309	USPAT; US-PGPUB	2004/07/13 12:58			0
62	BRS 4	(smart ic chip memory) near3 (card module) near5 ((single same one) near5 (chip ic monolithic)) and @pd>20040309	USPAT; US-PGPUB	2004/07/13 13:00			0
63	BRS 0	(smart ic chip memory) near3 (card module) near5 (single same one) near5 (chip ic monolithic) near5 (control\$3 process\$3 microprocess\$3 microcontrol\$3) and @pd>20040309	USPAT; US-PGPUB	2004/07/13 13:03			0
64	BRS 4	(smart ic chip memory) near3 (card module) near5 (single same one) near5 (chip ic monolithic circuit) and @pd>20040309	USPAT; US-PGPUB	2004/07/13 13:03			0
65	BRS 10	(smart memory) near3 (card module) near5 (stack\$3 near5 (chip ic)) and @pd>20040309	USPAT; US-PGPUB	2004/07/13 13:06			0

	Type Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
66	BRS 1099	257/777.ccls. not (257/433.ccls. 257/679.ccls. 361/737.ccls. 902/25.ccls. 902/26.ccls. 902/29.ccls. 235/492.ccls. 235/441.ccls.)	USPAT; US-PGPUB	2004/07/13 14:14			0

	Type Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
68	BRS 0	(Chhor-Khushraw-S.in. Moresco-Larry-L.in.) and @pd>20040713	USPAT; US-PGPUB; EPO; JPO	2004/09/27 15:32			0
69	BRS 193	(257/777.ccls. 257/433.ccls. 257/679.ccls. 361/737.ccls. 902/25.ccls. 902/26.ccls. 902/29.ccls. 235/492.ccls. 235/441.ccls.) and @pd>20040713	USPAT; US-PGPUB	2004/09/23 17:25			0
70	IS&R 1	("6731011").PN.	USPAT; US-PGPUB	2004/09/23 15:51			0
71	BRS 892	257/686.ccls. not (257/777.ccls. 257/433.ccls. 257/679.ccls. 361/737.ccls. 902/25.ccls. 902/26.ccls. 902/29.ccls. 235/492.ccls. 235/441.ccls.)	USPAT; US-PGPUB	2004/09/27 10:48			0
72	BRS 1	"5422435".PN.	USPAT	2004/09/27 09:46			0
73	BRS 9	6316727.URPN.	USPAT	2004/09/27 09:50			0
74	BRS 12	("5012323" "5114880" "5147815" "5471369" "5479051" "5689135" "5804874" "5917242" "6080264" "6087722" "6118176" "6175149").PN.	USPAT	2004/09/27 10:07			0
75	BRS 16	6297547.URPN.	USPAT	2004/09/27 10:14			0
76	BRS 1173	257/676.ccls. not (257/686.ccls. 257/777.ccls. 257/433.ccls. 257/679.ccls. 361/737.ccls. 902/25.ccls. 902/26.ccls. 902/29.ccls. 235/492.ccls. 235/441.ccls.)	USPAT; US-PGPUB	2004/09/27 14:22			0
77	BRS 1367	174/52.4.ccls. not (257/676.ccls. 257/686.ccls. 257/777.ccls. 257/433.ccls. 257/679.ccls. 361/737.ccls. 902/25.ccls. 902/26.ccls. 902/29.ccls. 235/492.ccls. 235/441.ccls.)	USPAT; US-PGPUB	2004/09/27 14:24			0

	Type Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
78	BRS 10	((smart ic chip memory) near3 (card module) same (resin near5 mold\$3)) same (conduct\$3 connect\$3 terminal\$1 pad\$1 contact\$3) and @pd>20040713	USPAT; US-PGPUB	2004/09/27 15:34			0
79	BRS 0	(smart ic chip memory) near3 (card module) same (resin near5 mold\$3) same (conduct\$3 connect\$3 terminal\$1 pad\$1 contact\$3) and @pd>20040713	EPO; JPO; DERWENT; IBM_TDB	2004/09/27 16:02			0
80	BRS 2	((smart ic chip memory) near3 (card module) same (resin epoxy)) same (lead adj frame) and @pd>20040713	USPAT; US-PGPUB	2004/09/27 16:03			0
81	BRS 0	((smart ic chip memory) near3 (card module) same (resin epoxy)) same (lead adj frame) and @pd>20040713	EPO; JPO; DERWENT; IBM_TDB	2004/09/27 16:04			0
82	BRS 1	(smart ic chip memory) near3 (card module) same (plate near5 (thermal\$2 heat) near5 conductive) and @pd>20040713	USPAT; US-PGPUB	2004/09/27 16:05			0
83	BRS 1	(smart ic chip memory) near3 (card module) same (plate near5 (thermal\$2 heat) near5 conductive) near5 (packag\$3 resin cas\$3)) and @pd>20040713	USPAT; US-PGPUB	2004/09/27 16:06			0
84	BRS 5	(smart ic chip memory) near3 (card module) same (memory near5 controller near5 (single same one)) and @pd>20040713	USPAT; US-PGPUB	2004/09/27 16:07			0
85	BRS 4	(smart ic chip memory) near3 (card module) near5 ((single same one) near5 (chip ic monolithic)) and @pd>20040713	USPAT; US-PGPUB	2004/09/27 16:23			0
86	BRS 0	(smart ic chip memory) near3 (card module) near5 (single same one) near5 (chip ic monolithic) near5 (controll\$3 process\$3 microprocess\$3 microcontroll\$3) and @pd>20040713	USPAT; US-PGPUB	2004/09/27 16:35			0

	Type Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
87	BRS 4	(smart ic chip memory) near3 (card module) near5 (single same one) near5 (chip ic monolithic circuit) and @pd>20040713	USPAT; US-PGPUB	2004/09/27 16:36			0
88	BRS 3	(smart memory) near3 (card module) near5 (stack\$3 near5 (chip ic) and @pd>20040713	USPAT; US-PGPUB	2004/09/27 16:41			0
89	IS&R 5	((("6316727") or ("5422435") or ("6297547")) or ("5012323") or ("5172214")).PN.	USPAT; US-PGPUB	2004/09/28 11:04			0